## PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

| 28   |      |       |      |
|------|------|-------|------|
| No28 | Date | 12.06 | 2020 |

It is certified that an inspection team headed by Er. Samir Subhash Dung Dung, Assistant Engineer (Name of Officers with designation) from D.W & Sub Division, Chakradharpur (Name of Department/Office) inspected the Madhusudan Mahto High School Asantalia, Chakradharpur (Name & Address of The School) on 12.06.2020 and found that the Madhusudan Mahto High School Asantalia, Chakradharpur (Name of School) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T Govt.

The above valid for a period of One Year

Signature with seal :...

D:W. & S Sub-

Name

: Samir Subhash Dung Dung

Designation

: Assistant Engineer

To

Madhusudan Mahto

High School Asantalia,

Chakradharpur

(Name & address of the Institution)